

Oil Field Environmental Incident Summary

Incident: 20140421113336 **Date/Time of Notice:** 04/21/2014 11:33

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: LK-BICE- 147-97-1201H-6

Field Name: BIG GULCH

Well File #: 26307

Date Incident: 4/20/2014

Time Incident: 12:30

Facility ID Number:

County: DUNN

Twp: 147

Rng: 97

Sec: 12

Qtr:

Location Description: While conducting rig move operations on the LK-BICE-147-97-1201H-6 location, approximately 1.50 bbls of salt water was released on the location and on the county road adjacent to the location. Approximately 1 bbl of salt water was released on the LK-BICE-147-97-1201H-6 location, and approximately 15 - 20 gallons of salt water was released on the county road (10 St. NW). A three sided tank that still had salt water in it was moved from the LK-BICE-147-97-1201H-6 location, and this was source of the release of salt water. The impacted material at the location and on the county road will be excavated, stockpiled, and transported to a properly permitted disposal facility.

Submitted By: Jason Henry

Received By:

Contact Person: Jason Henry
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.2 Mile

Distance Nearest Water Well: 0.2 Mile

Type of Incident: Tank Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	1.5	Barrels	1.5	Barrels	1.5	barrels
Other						

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 10/19/2015 **Clean Up Concluded:** 4/21/2014

Risk Evaluation:

N/A

Areal Extent:

The released salt water was observed on the county road for an approximate distance of 0.5 miles.

Potential Environmental Impacts:

The release occurred above ground, and there were no potential receptors observed in the immediate vicinity of the release location. The impacted material at the location and on the county road will be excavated, stockpiled, and transported to a properly permitted disposal facility.

Action Taken or Planned:

The impacted material at the location and on the county road will be excavated, stockpiled, and transported to a properly permitted disposal facility.

Wastes Disposal Location: At a properly permitted disposal facility.

Agencies Involved:***Updates***

Date: 4/21/2014 ***Status:*** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

A portion of the released salt water was lost on a county road. Followup is necessary.

Date: 4/23/2014 ***Status:*** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The weather was 53 °F, with wind from the northwest twenty plus miles per hour. The area has been cleaned up and the line is repaired. There is still a small pile of hydro vac soil on site within a temporary containment area on southeast corner of site. There are still some roll off containers on site that appear empty. Could not see any impacts to the gravel road, there is a lot of traffic along this road. No further follow-up needed at this time